


CORNER RESTORATION

S.W. 1/16 Cor.
CORNER Sec. 29 TWP 15S RANGE 32E

ORIGINAL SURVEY BY:

CONTRACT NUMBER: S.W. 1/16 Cor. Sec. 29, not
previously established.

CONTRACT DATE:



ORIGINAL DESCRIPTION:

S.W. 1/16 not previously established.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. Gentis

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

May 4, 1976

Grant County Surveyor

EVIDENCE FOUND:

Not applicable

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a 5/8"x30" iron pin 26" in the
ground for S.W. 1/16 Sec. 29, from which I scribe
NEW BT's:

A 9" pine brs. N. 69° W., 33.5 ft. dist. mkd. SW 1/16S29CSBT.
A 6" pine brs. S. 21° W., 13.2 ft. dist. mkd. SW 1/16S29CSBT.
Corner is approximately 230 ft. West of fence corner.
Fences run North and East.

I used a compass with a 20° East variation and a steel tape,
measuring to face of BT's.

MONUMENT MARKED



RECEIVED AND
FILED

DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk

By _____ Deputy

See map of Survey No. 398.