

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1976 by, PLS598, map of survey 398.

DIAGRAM

T15S R32E
S1/16 C S29
C
1983
PLS848

Description of corner evidence found:

Found 5/8" iron pin protruding from ground 5", no marks, accepted pin as 1/16 corner as established from map of survey 398, due to harmony with surrounding corners.

Description of monument and accessories established to perpetuate the original location of this corner:

Scribed bearing trees:

A Pine 14" dia. bears S25°, 12'W, 51.1 ft scribed C S1/16 S29 BT.

A Pine 16" dia, bears N14°, 28' 81.0 ft. scribed C S1/16 S29 BT.

Nailed brass washers stamped PLS848, bearing tree & warning signs to each tree.

Set steel posts with warning & boundry signs 1.7 ft., East from pin.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 4-6-83

Witnessed by D. Mitchell Ferguson.

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 1 day of June, 1983
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)

See Survey # 773