


CORNER RESTORATION

SW Cor.
CORNER Sec. 29 TWP 15S RANGE 32E

ORIGINAL SURVEY BY: Samuel W. Lackland

CONTRACT NUMBER: 384

CONTRACT DATE: March 3, 1881



ORIGINAL DESCRIPTION:

80.00 set stone 15x12x4 in a mound of stone for the cor. to Secs. 29, 30, 31 and 32. From which:



A pine 12" in diam. brs. N. 36° E., 27 lks. dist.

A pine 40" in diam. brs. S. 40° E., 29 lks. dist.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Baggett
W. Gentis



DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy

April 23, 1976

Grant County Surveyor

EVIDENCE FOUND:

I found the original section corner a basalt stone 4x14x12 inches marked with 5 notches on East and 1 notch on South edge, firmly set in a mound of stone, from which the Original Bearing Trees:

A 27" pine bears N. 45° E., 17.5 feet with scribing visible in blaze that I opened.
A 30" pine, dead and down, bears S. 32° E., 21.0 ft. No marks visible.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: I set a 1½"x30" iron pipe 28" in the ground with brass cap marked as shown, from which I scribe NEW BT's:

A 30" pine bears S. 26° E., 35.4 ft. mkd. T15SR32ES32CSBT.
A 4" pine bears S. 53° W., 16.5 ft. mkd. S31CSBT.
A 28" pine bears N. 10° W., 47.0 Ft. mkd. T15SR32ES30CSBT.

I buried the original corner stone South and alongside the iron pipe and surrounded pipe with a mound of stone. I used a compass with 20° East variation and steel tape, measuring to the face of the bearing tree blaze.

MONUMENT MARKED

