


CORNER RESTORATION


S.W. Cor
CORNER Sec. 28 TWP 15 S., RANGE 32 E.
ORIGINAL SURVEY BY: Samuel W. Lackland
CONTRACT NUMBER: 384
CONTRACT DATE: Mar. 29, 1881



ORIGINAL DESCRIPTION:
80.00 Set stone 16 x 12 x 4 in md. of stone for cor. to Secs. 28, 29, 32 & 33
From Which: A Fir 8 in. diam. brs. N76°W. 13 lks dist.
A Pine 36 in. diam. brs. S20°E. 74 lks dist.

RESTORATION BY, STAMP AND DATE:

R. D. BAGETT
W. GENTIS



FEB. 22, 1976 GRANT COUNTY SURVEYOR

EVIDENCE FOUND:

I did not find the original corner stone.
I establish corner at record bearing and dist. from one remaining Orig. BT which is a 12" pine that brs. N. 76° W. 8.6 ft. mkd. S29T15R32 BT in open blaze. Found no evidence of other BT.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

At Corner Point: Set 1½" x 30" iron pipe 24" in ground
in md. of stone, with brass cap mkd as shown.

From Which: NEW BTs
A 7" fir brs. N. 79° E., 11.3 ft. dist. mkd T15SR32E S28 CSBT
A 8" fir brs.S. 35° E., 20.6 ft. dist. mkd T15SR32E S33 CSBT
A 27" fir brs.S. 25° W., 47.5 ft. dist. mkd. T15SR32E S32 CSBT

Used compass with 20° East Var. and steel tape measuring to face of BT blaze.

MONUMENT MARKED



RECEIVED AND
FILED

NOV 29 1976

See Map of Survey No. 398

JOHN LIVEIRA, County Clerk
By *Debra L. Simon* Deputy