


CORNER RESTORATION

S.W. Cor.
CORNER Sec. 34 TWP 15 S., RANGE 32 E.

ORIGINAL SURVEY BY: Henry Cooke

CONTRACT NUMBER:

CONTRACT DATE: 1880



ORIGINAL DESCRIPTION:

80.00 Set post for corner to Secs. 33 & 34

From which:

A pine 24 in. diam. brs. N 80° E 50 lks. dist.

A Pine 20 in. diam. brs. N 20° W 64 lks. dist.

RESTORATION BY, STAMP AND DATE:

R. D. BAGETT
W. GENTIS

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

FEB. 1976

GRANT COUNTY SURVEYOR

EVIDENCE FOUND:

Found remains of 2 Orig. BTs. Did not find Orig. corner post.

A dead and down 20" pine brs. N 20° W, 42.2 ft. dist. scribing and axe marks visible.

A 24" pine stump (remains) brs. N 61° E, 33.0 ft. with scribing and axe marks visible.

I establish corner at record bearing and dist. from N.W. BT. and at record dist. from N.E. BT.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 1½" x 30" iron pipe 26' in the ground with brass cap mkd as shown.

MONUMENT MARKED

From Which: NEW BTs.

A 9" Fir brs. N. 10° E. 13.2 ft. mkd T15SR32E SC S34 CSBT

A 8" Pine brs. N. 35° W. 37.8 ft. mkd T15SR32E SC S33 CSBT

Used compass with 20° East Var. and Steel tape measuring to face of B.T. blaze.

See Map of Survey No. 398

RECEIVED AND
FILED

NOV 29 1976

JOHN LIVEIRA, County Clerk

By *Lauren Lemmon* Deputy

