

# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner was established by Homer D. Angell, US Deputy Surveyor, during the original survey Contract No. 725 dated March, 1901.

Set a basalt stone, 15x12x4 ins., 10 ins. in the ground, for cor. of secs. 19, 24, 25 & 30, marked with 4 notches on the N. and 2 notches on the S. edges from which (See the BT information in the 1939 survey notes)

## DIAGRAM.

|      |      |
|------|------|
| T15S |      |
| R33E | R34E |
| S24  | S19  |
| S25  | S30  |

1939

Corner was monumented by George F. Rigby, US Deputy Surveyor, during a dependent resurvey Group No. 215 dated March, 1938.

The corner is a basalt stone, 16x12x3 ins., firmly set, mkd. with 4 notches on N. and 2 notches on S. edges.

Set an iron post, 3 ft. long, 2 ins. diam., 22 ins. in the ground to bedrock, with the original stone deposited at the base, and in a mound of stone to top, for cor. of secs. 19, 24, 25 and 30, with brass cap mkd. (as shown in the diagram) from which

- A pine, 48 ins. diam., bears (Orig 40° Pine, N7°E, 90 lks) N7° 30'E, (59.4') 90 lks. dist., (Old BT) mkd. T15SR34E S19 BT
- A fir, 28 ins. diam., bears (Orig 24° Spruce, S55°E, 44 lks) S54° 30'E, (27.7') 42 lks. dist., (Old BT) mkd. T15SR34E S30 BT
- A pine, 12 ins. diam., bears (Orig 12° Pine, S10°W, 22 lks) S11° 15'W, (14.5') 22 lks. dist., (Old BT) mkd. T15SR33E S25 BT
- A fir, 38 ins. diam., bears (Orig 14° Fir, N34 1/2°W, 116 lks) N33° 00'W, (76.6') 116 lks. dist., (Old BT) mkd. T15SR33E S24 BT

## Description of corner evidence found:

1939 GLO 2 1/2" Brass Cap on a 1" galvanized pipe in a rock mound surrounding the monument.

- 38" Western larch (Dead) (Scribing Visible) (1939 BT) bears N7° 15'E, 59.7 feet. Wrong species call in both earlier surveys.
- 36" White fir (Fair Condition) (Scribing Visible) (1939 BT) bears S53° 15'E, 27.8 feet.
- 17" Lodgepole pine (Dead) (Scribing Visible) (1939 BT) bears S12°W, 14.8 feet.
- 28" White fir (Fair Condition) (Scribing Visible) (1939 BT) bears N33° 30'W, 76.5 feet.

## Description of monument and accessories I established to perpetuate the original location of this corner:

Maintained the monument by checking it for firmness and making two new BTs.

The mound needed no improvement and was found to be 36" in diameter by 12" high around the monument, from which new BTs are:

- 10" Western larch bears S74°W, 16.2 feet scribed T15SR33E S25 BT
- 9" Lodgepole pine bears N17° 30'E, 17.6 feet scribed T15SR34E S19 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on October 25, 1987, I monumented the corner as herein described.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 12 DAY OF Nov, 1987

Robert D. Bayot  
Grant County Surveyor