


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1900 by George R. Campbell
Set 40"x20"x20" stone, 30" in ground for 1/4 Section corner
marked 1/4 in west face from which:
a red fir, 26" in diam. bears N78°E, 98 lks.
a yellow pine, 40" in diam. bears S 85°W, 8 lks.



Description of corner evidence found:

40" P.Pine stump, N80°W, 7.1', Scribed 1/4 S8, B.T.
38" Fir, N83°E, 63.3', Scribe scar, did not open

Found original stone 30"x20"x20" with 1/4 scribed in north face, set 20" in ground.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2" Brass Cap on 2" galvanized pipe 18" in ground with mound of stone to cap. Buried original stone on west side of monument.



New Bearing trees:

6" Fir, N29°E, 13.0', Scribed 1/4 S9, B.T.
12" Fir, S84°W, 13.6', Scribed 1/4 S8, B.T.

All B.T.'s have sign 54-4 & 54-3 attached. Set steel guard post with 54-9 sign. Painted red band around bearing trees. Tagged trees with L.S. 980 washer.

MONUMENT STAMPED:

Witnesses: David Scott, Party Chief
Richard Larson, Chainman



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 14 day of Jan, 1981
Robert D. Dwyer by _____
(COUNTY OFFICIAL) (DEPUTY)