

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by George R. Campbell, US Deputy Surveyor, during the original survey Contract No. 724 dated September, 1900.

A white fir 15 ins. diam. for 1/4 sec. cor., I mark 1/4 S19 on W side, 20 on E side from which

A white fir 10 ins diam bears S65°E, (5.3') 8 lks dist. marked 1/4 S BT

A white fir 10 ins diam bears N55°W, (11.2') 17 lks dist. marked 1/4 S BT

Corner was maintained by Howard E. Taylor, RPE 2891, during a retracement survey dated August, 1957.

Found original marked 15" W. Fir for corner and I set stone 20x17x12 with 1/4 on south side against east edge of base of corner tree. The original 10" W Fir S65°E lks is now about 14" and ok. The Orig. 10" W Fir N55°W 17 lks. is a windfall. I scribed

34" W Fir S40°W, 29.0 feet "S 29" 1/4 S"

Description of corner evidence found:

Found the original corner tree to be a 24" White fir in good condition with both blazes healed over. Also found the Taylor stone set on the south side of the tree. A forest fire moderately burned the area around this corner location between my preliminary traversing and the setting of the corner monument.

21" White fir (Good Condition)(Blaze Healed Over)(1900 BT) bears S70°30'E, 5.3 feet.

36" White fir (24" Stump)(Scribing Visible)(1957 BT) bears S35°30'W, 29.7 feet. All BT bearings and distances are measured from the Corner Tree.

10" white fir (1900 BT) not found.

DIAGRAM

T15S R35E

NORTH ↑ 4.3'
RM

1/4 CORNER TREE
1990
PLS 699

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 28" in the ground, as a Reference Monument to the 1/4 Corner Tree, which tree has a red-band painted around it, the blazes are painted red and attention signs attached on the north and south sides. Built a mound of rock to be 30" in diameter by 2" high around the monument.

10" White fir bears S75°W, 51.0 feet scribed 1/4 S19 BT

Attached BT and an Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation that was made on the adjacent McCoy Cadastral Survey contract in 1987, to stamped brass washers nailed on new BTs in the scribed red-painted blazes or to the red-painted blazes or scars on old BTs. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set steel fence posts 3.4 feet S and 6.2 feet N of the Reference Monument on the National Forest boundary lines. Attached Forest Boundary signs to each post and an Attention sign to the S post.

I, Leland L. Myers, 587 E. Auburn St., P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 24, 1990, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 30 DAY OF NOV, 1992.

Robert D. Baggett
Grant County Surveyor

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

MAP OF SURVEY No. 1197