

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Eugen P. McCornack, Under General Land Office Contract No. 398. Surveyor Generals Notes State: Set post 3 ft. high 3 ins. square 24 ins. in the ground for standard $\frac{1}{4}$ sec. cor. marked SC $\frac{1}{4}$ S on North face.

From which:

A Pine 36 ins. diam. bears S45°W, 15 lks. dist. marked SC $\frac{1}{4}$ S BT.

A Pine 24 ins. diam. bears N10°W, 60 lks. dist. marked SC $\frac{1}{4}$ S BT.

DIAGRAM

SC
T15S R36E
 $\frac{1}{4}$ S34
1983
PLS 848

Description of corner evidence found:

Found rotten remains at a wood post in post hole.

From which:

A Pine stump 36" dia. with scribing, reads BT. bears S45°W, 10.0 ft. to face of blaze.

A Pine 31" dia. live in good condition with blaze healed over bears N7°W, 40.10 ft. to blaze face.

Accepted remains of post in hole as the S.C. $\frac{1}{4}$ cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30" x 2" aluminum pipe with a 3 $\frac{1}{2}$ " aluminum cap stamped as shown in diagram.



Set 20" in the original post hole.

From which:

A Pine 31" dia. (the original bearing tree) bears N7°W, 40.6 ft. New scribing reads $\frac{1}{4}$ S34 SC BT.

Set a steel post with warning sign North 4.8 ft.

Nailed brass washers stamped PLS 848, bearing tree & warning signs to each tree.



Date June 14, 1983

Witnessed by D. Mitchell Ferguson

Office of.....Surveyor..... County of.....Grant.....

State of.....Oregon....., I hereby certify that the within instrument was filed in this office

for record on the..29th day of.....August....., 19..83.

.....*Robert L. Beyer*..... by
(COUNTY OFFICIAL) (DEPUTY)