CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Mark A. Fullerton under his General Land Office contract No. 395.

Surveyor General's records state:
Set basalt stone 14 x 10 x 5 in stone mound for cor. to sec.s 16, 17, 20 & 21.

DIAGRAM

T15S	R26E
S17	S16
S20	S21

Description of corner evidence found:

Found stone 14 x 10 x 5 in stone mound with 4 notches on East edge & 3 notches on South edge.

Description of monument and accessories I established to perpetuate the original location of this corner

Hit solid rock 4" deep. Marked "X" in rock. Set 2½" x 30" Alum. pipe with 3" Alum. cap over "X", set orig. stone next to pipe and built mound of stone around pipe. Cap is marked as shown:

T15S	R26E
S17	S16
S20	S21

RLS 1104 1979

A Juniper, 6 in. dia., bears N34°E 139.1', scribed T15S R26E S16, B.T.
A Juniper, 13 in. dia., bears S57°E 49.6', scribed T15S R26E S21, B.T.
A Juniper, 9 in. dia., bears S5°W 110.4', scribed T15S, R26E S20, B.T.
A Juniper, 10 in. dia., bears N64°W 287.1' scribed T15S R26E S17, B.T.

REGISTERED PROFESSIONAL LAND SURVEYOR
James R. Tye
OREGON
JULY 22, 1977
JAMES R. TYE
1104

Witness to Corner: Larry Wiley
Larry Wiley
L.S.I.T.

I hereby certify the above monument was re-established as herein described on 6-15-79.

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 23 day of Aug., 1979, at 1:30 o'clock P.m., (signed)
Robert D. Bagett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/66)