CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM
T15SR26E
1/4
S27+S26
W.M.
GRANT CO., OR.

Corner established by Mark A. Fullerton, Deputy Surveyor, under General Land Office Contract No. 395 dated May 25, 1881, and performed during that year. Surveyor General's records state:
North on line betw. secs 26 X 27
40.00 Set basalt stone 12X8X6 in stone mound for 1/4 sec cor.
Corner re-established by Thomas E. Casinger & Rick E. Tawny, Cadastral Surveyors, under special instructions dated Sept. 19, 1980, under Group 1041, Oregon. Official B.L.M. records state: N.0°15'E., Bet. secs. 26 and 27 40.81 Point for the 1/4 sec. cor. of secs. 26 and 27, at proportionate distance; there is no remaining evidence of the original corner. Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 12 ins. in the ground, to bedrock, supported in a mound of stone, 3 ft. base, to top, with aluminum cap mkd. T15SR26E from which: a juniper, 15 ins. diam, bears

Description of corner evidence found: 1/4 S27+S526 1981 N. 30 1/2° E., 49 lks. dist., mkd. 1/4S26BT. a juniper, 10 ins. diam., bears S. 31° W., 68 lks. dist., mkd. 1/4S27BT.

At corner location found broken off aluminum pipe 26 inches long bent over in stone mound 3 foot diameter. Excavated stone mound finding the base of the pipe still firmly in position secured by stones. Found the S.E. bearing tree, an 11" Juniper bears South 31°00' West, 45.1 ft., visible scribing-1/4S27BT on open face. Found the remains of the N.E. bearing tree, a 16" Diam. sawed Juniper stump 24" high bears North 30°30' East, 32.3 ft., visible scribing-1/4S26BT- on open face, remainder of tree alongside.

M.V. 18°00' East

Description of monument and accessories I established to perpetuate the original location of this corner:

T15SR26E
1/4
S27|S26
LS 1026
1985

At position of base of recovered aluminum pipe monument, set 2 1/2 inch O.D. X 30 inch long aluminum pipe 12 inches in ground to bedrock with 3 1/4 inch aluminum cap with standard markings marked as shown:
Marked new bearing tree:
a 17" Juniper bears South 14°00' East, 43.5 ft., scribed -1/4S26BT.
Raised stone mound 4 foot diam. to cap. Set steel post 5 feet North with sign 54-4 facing corner. Painted red band and faces red on both new and B.L.M. bearing trees and nailed signs 54-3 and 54-4 to all bearing trees. Nailed brass washer stamped-A.S.&E. LS 1026- to face of new bearing tree.

I hereby certify the above corner monument was re-established as herein described on June 28, 1985, at the request of B & S Logging, Prineville, Oregon.
Witnesses: David B. Armstrong
Andrew J. Dodson

REGISTERED
PROFESSIONAL
LAND SURVEYOR
David B. Armstrong
7/1/85 OREGON
AUGUST 22, 1975
DAVID B. ARMSTRONG
1026

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 8th day of July, 1985
Robert D. Bagett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

T-17