RECORD OF LAND CORNER MONUMENTATION



CORNER: Standard Corner–S¼ Cor. Sec. 33, T.15S., R.26E., W.M.

ORIGINAL SURVEY BY: Alonso Gesner

CONTRACT NUMBER: 206

CONTRACT DATE: July 10, 1874

SUBSEQUENT SURVEYS: Mark A Fullerton 1881, C. Albert White 1957

ORIGINAL G.L.O. DESCRIPTION: Set stone 16x12x8 for ¼ sec. cor.

1881 RESURVEY BY MARK A. FULLERTON, U.S. DEPUTY SURVEYOR UNDER HIS CONTRACT NO. 395, DATED 05/25/1881: to stone 16x12x8, for ¼ sec. cor. Raised stone mound at cor.

1957 RESURVEY BY C. ALBERT WHITE, CADASTRAL SURVEYOR UNDER SPECIAL INSTRUCTIONS DATED 10/3/1957 INCLUDED UNDER GROUP NO. 359 (Pg. 319): SEE RECORD MAP OF SURVEY NO. 58.

The standard $\frac{1}{4}$ sec. cor. of sec. 33, monumented with an unmarked basalt stone, 14 x 10 x 6 ins., firmly set in a mound of stone, 4 ft. diam., 18 ins. high.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 4 ins. in the ground to bedrock, and in a mound of stone, 4 ft. base, to top, with brass cap mkd.

S C
T 15 S R 26 E
$\frac{1}{4}$ S 33
1960

from which

A juniper, 7 ins. diam., bears N. 4° E., 106 lks. dist., mkd. $\frac{1}{4}$ S33 SC BT.

A juniper, 8 ins. diam., bears N. 60° W., 100 lks. dist., mkd. $\frac{1}{4}$ S33 SC BT.

Deposit original corner stone alongside iron post.

EVIDENCE FOUND:

None. No field visit was made for this Corner Restoration Report, it has been prepared from record General Land Office and Bureau of Land Management field notes. See Record Map of Survey 58 filed in the Grant County Surveyor's Office.

PREPARED BY:
Michael C. Springer, PLS
Grant County Surveyor
Marcus Teague, Technician

217 N. Canyon Blvd.
John Day, OR, 97845
(541) 575–1251

January 9, 2017

RECEIVED AND FILED
GRANT COUNTY SURVEYOR
JAN 30 2017
BY:

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918
EXPIRES: 6/30/2018