RECORD OF LAND CORNER MONUMENTATION



CORNER: Standard Corner–S¼ Cor. Sec. 36, T.15S., R.26E., W.M.

ORIGINAL SURVEY BY: Alonso Gesner

CONTRACT NUMBER: 206

CONTRACT DATE: July 10, 1874

SUBSEQUENT SURVEYS: Mark A Fullerton 1881, C. Albert White 1957

ORIGINAL G.L.O. DESCRIPTION: Set stone 12x10x8 for ¼ sec. cor.

1881 RESURVEY BY MARK A. FULLERTON, U.S. DEPUTY SURVEYOR UNDER HIS CONTRACT NO. 395, DATED 05/25/1881: to stone 12x10x8 for ¼ sec. cor. Raised stone mound at cor.

1957 RESURVEY BY C. ALBERT WHITE, CADASTRAL SURVEYOR UNDER SPECIAL INSTRUCTIONS DATED 10/3/1957 INCLUDED UNDER GROUP NO. 359 (Pg. 322–323): SEE RECORD MAP OF SURVEY NO. 58.

Point for the standard ¼ sec. cor. of sec. 36, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

S C
T 15 S R 26 E
¼ S 36
1959

from which

A fir, 4 ins. diam., bears N. 35½° W., 66 lks. dist., mkd. ¼ S36 SC BT.

No tree available to the NE.

EVIDENCE FOUND:
None. No field visit was made for this Corner Restoration Report, it has been prepared from record General Land Office and Bureau of Land Management field notes. See Record Map of Survey 58 filed in the Grant County Surveyor's Office.

PREPARED BY:
Michael C. Springer, PLS
Grant County Surveyor
Marcus Teague, Technician

217 N. Canyon Blvd.
John Day, OR, 97845
(541) 575–1251

January 9, 2017

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

JAN 30 2017

BY: _____

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2018