CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Standard Corner

DIAGRAM

T. 15 S. R. 29 E.

35 | 36

1

T. 16 S. R. 29 E.

History of original corner establishment:

Corner originally established by Eckelsen, under joint contract #328, dated June 20, 1879.

Surveyor General's records state: Set post from which;
a pine 48" in diameter bears N 15° E 39 links distance
a pine 30" in diameter bears N 60° W 140 links distance

Description of corner evidence found:

Found evidence of original post in the ground.

Found dead and down ponderosa pine 50" in diameter N 15° E 39 links, scribed "S36 15 R29" "BT"

Found alive with open face ponderosa pine 37" in diameter N 71° W 140 links distance, scribed "S35 T15 R29"

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2½"x30" aluminum pipe with a 3¼" aluminum cap 26" in ground. Cap marked;

T15S R29E
SC
S35|S36
S1
T16S R29E
1981
RLS 1664

Bearing trees

a ponderosa pine 11" in diameter bears N 88½° W 16.5 feet distance, scribed "T15SR29ES35SC" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.

a ponderosa pine 13" in diameter bears N 36½° E 48.1 feet distance, scribed "T15SR29ES36SC" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.

Compass declination 18° East

Note

I set a steel fence post with USFS Attention sign at corner, Placed USFS bearing tree signs on all bearing trees, and painted red band on smooth bark at breast height on all bearing trees.

I hereby certify the above corner location was perpetuated as herein described on June 18, 1981.

Terry Butler, Witness

REGISTERED PROFESSIONAL LAND SURVEYOR

Carl E. Sundet

OREGON
JULY 14, 1978
CARL E. SUNDET
1664

Office of Surveyor County of Grant

State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 23 day of Oct, 1981

Robert D. Padgett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—799-276