CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-23

History of original corner establishment:

Original survey was by Sam W. Lackland under GLO Contract No. 384, dated March 29, 1881..

Set post for 1/4 Sec. Corner from which a Pine 12" in dia. bears N85°E, 23 lks. dist..
A Pine 10" in dia. bears S21°W, 60 lks. dist.

DIAGRAM

T15S R29E

S25
1/4
S36

Description of corner evidence found:

A diligent search was made and no evidence of the corner or its accessories could be found.

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point:
Set 2½"x30" galvanized pipe with brass cap stamped:
Set pipe 24" in ground with mound of stone to cap.

A Ponderosa Pine 6" in dia. bears N7°E, 13.7 ft., scribed 1/4 S25 BT.
A Ponderosa Pine 6" in dia. bears S12°W, 5.5 ft., scribed 1/4 S36 BT.
Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs orange. Attached 54-4 and 54-2 signs to metal fence post 5 ft. east of corner.

T15S R29E WM
S25
1/4
S36
1979
OR PLS 1294

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1294

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Rodger Orton
Glen Wagoner
Jeff Anderson

August 1, 1979

Office of County Surveyor *County of* Grant
State of Oregon *, I hereby certify that the within instrument was filed in this office for record on the* 4 *day of* Oct *, 19* 79
Robert D Bagett *by* .....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO—798-276

V-23