


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established by the General Land Office Survey.



A-23
F.B.2 Pgs.4 & 5

Description of corner evidence found:

Corner not previously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate position as determined by survey, set 2-1/2 inch O.D. X 30 inches long aluminum pipe 12 inches in ground to bedrock with 3 inch aluminum cap marked as shown:


Marked bearing trees:

A 19" Ponderosa Pine bears South 82-1/4° West, 166.6 ft., scribed-1/4S1BT;
A 12"x16" double Juniper bears South 20° West, 248.5 ft., scribed-1/4S1BT.

Raised stone mound 3 feet diam. to cap. Set steel post 5 feet West with sign 54-9 facing cap. Painted red band and faces red and nailed signs 54-3 and 54-9 to BT's. Nailed brass washer stamped "AS&E LS1026" to face of BT's.

I hereby certify that the above corner monument was established as herein described on June 2, 1987.

Witnesses: David B. Armstrong
Shelby H. Griggs



M.V.19-1/2°E.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Armstrong

6/26/87 OREGON
AUGUST 22, 1975
DAVID B. ARMSTRONG
1026

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the Aug day of Aug, 1987
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)