


CORNER RESTORATION

CORNER: NW Cor. Sec. 11 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Samuel W. Lackland

CONTRACT NUMBER: 415

CONTRACT DATE: August 19, 1881



Subsequent surveys:

- Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set basalt stone 18x12x5 ins. 14 ins. in ground for Cor. to Secs. 2, 3, 10 & 11. Marked with 5 notches on S and 2 notches on E edges. Raised Mound of Stone 2½ ft. high and 5 at base alongside.

► 1975:

Point for the cor. of secs. 2, 3, 10, and 11, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 16 S R 27 E
S 3 | S 2
S 10 | S 11
1976

from which

A ponderosa pine, 17 ins. diam., bears N. 68° E.,
63 lks. dist., mkd. T16S R27E S2 BT.

A ponderosa pine, 19 ins. diam., bears S. 81° E.,
48 lks. dist., mkd. T16S R27E S11 BT.

A ponderosa pine, 15 ins. diam., bears S. 33° W.,
70 lks. dist., mkd. T16S R27E S10 BT.

A juniper, 14 ins. diam., bears N. 54° W., 37 lks.
dist., mkd. T16S R27E S3 BT.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

NOV 12, 2010

BY:



EXPIRES: 6/30/2012

November 12, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.