


CORNER RESTORATION

CORNER: W1/4 Cor. Sec. 11 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Samuel W. Lackland

CONTRACT NUMBER: 415

CONTRACT DATE: August 19, 1881



Subsequent surveys:

- Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set basalt stone 15x10x7 ins. 12 ins. in ground for 1/4 Sec Cor. Marked 1/4 on W. face. Raised Mound of Stone 2 ft. High and 3½ at base alongside.

- 1975: From the ¼ sec. cor. of secs. 10 and 11, monumented with the original basalt stone, 15 x 10 x 7 ins., firmly set 12 ins. in the ground, and in a mound of stone, 2 ft. base, 1 ft. high, mkd. ¼ on W. face.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 16 S R 27 E
S 10 ½ S 11
1976

from which

A ponderosa pine, 37 ins. diam., bears S. 82½° E., 58 lks. dist., mkd. ¼ S11 BT.

A ponderosa pine, 15 ins. diam., bears N. 19° W., 63 lks. dist., mkd. ¼ S10 BT.

Deposit corner stone alongside iron post.


Corner is located 160 lks. north of Deer Creek Road, dirt, 25 lks. wide, bears N. 60° E. and S. 60° W.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

NOV 12, 2010

BY: 

REGISTERED
PROFESSIONAL
LAND SURVEYOR


OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2012

November 12, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.