


CORNER RESTORATION

CORNER: N1/4 Cor. Sec. 21 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Samuel W. Lackland

CONTRACT NUMBER: 415

CONTRACT DATE: August 19, 1881



Subsequent surveys:

- Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set basalt Stone 16x12x8 ins. 12 ins. in ground for 1/4 Sec. Cor. Marked 1/4 on N. face. From which a Pine 26 ins. diam. bears N27°W, 15 lks dist Marked 1/4 S BT. A Pine 30 ins diam. bears N4°E, 52 lks dist. Marked 1/4 S BT.

- 1975: Point for the 1/4 sec. cor. of secs. 16 and 21, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 16 S R 27 E
1/4 S 16
S 21
1976

from which

A fir, 12 ins. diam., bears N. 75½° W., 4 lks. dist., mkd. 1/4 S16 BT.


A fir, 12 ins. diam., bears S. 8° E., 31 lks. dist., mkd. 1/4 S21 BT.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

DEC 3, 2010

BY: 



December 2, 2010

Grant County Surveyor

EVIDENCE FOUND: None. No field visit was made for this Corner Restoration Report, it is prepared from record information. See Record Map of Survey No. 889 filed in the office of the Grant County Surveyor.