


CORNER RESTORATION

CORNER: W1/4 Cor. Sec. 23 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Samuel W. Lackland

CONTRACT NUMBER: 415

CONTRACT DATE: August 19, 1881



Subsequent surveys:

- Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set basalt stone 16x6x6 ins. 12 ins. in ground for 1/4 Sec Cor. Marked 1/4 on W. face. From which A Pine 32 ins. diam. bears N50°E. 80 lks. dist. Marked 1/4 S BT. Raised Mound of Stone alongside.

► 1975:

The 1/4 sec. cor. of secs. 22 and 23, determined at record bearing and distance from the remains of the original bearing tree:

A ponderosa pine snag, 32 ins. diam., bears N. 50° E., 80 lks. dist., with scribe marks 1/4 S visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, and in a mound of stone, 2 ft. base, to top, with brass cap mkd.

T 16 S R 27 E
1/4
S 22 | S 23
1975

from which new bearing trees

A ponderosa pine, 8 ins. diam., bears N. 64° E., 60 lks. dist., mkd. 1/4 S23 BT.

A ponderosa pine, 12 ins. diam., bears N. 28 1/2° W., 46 1/2 lks. dist., mkd. 1/4 S22 BT.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

NOV 12, 2010

BY:



EXPIRES: 6/30/2012

November 12, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.