


CORNER RESTORATION

CORNER: W1/4 Cor. Sec. 25 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Samuel W. Lackland

CONTRACT NUMBER: 415

CONTRACT DATE: August 19, 1881



Subsequent surveys:

- Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set post 4 ft. long and 4 ins Square, 12 ins. in ground for 1/4 Sec Cor. Marked 1/4 S on W face. From which a Pine 6 ins. diam. bears N20°E, 25 lks. dist. Marked 1/4 S BT. A Juniper 6 ins. diam. bears N70°W, 10 lks dist. Marked 1/4 S BT

► 1975:

Point for the 1/4 sec. cor. of secs. 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 12 ins. in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T 16 S R 27 E
1/4
S 26 | S 25
1975

from which

A pine, 12 ins. diam., bears S. 67½° E., 100 lks. dist., mkd. 1/4 S25 BT.

A pine, 8 ins. diam., bears N. 70° W., 30½ lks. dist., mkd. 1/4 S26 BT.


RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

NOV 12, 2010

BY:



EXPIRES: 6/30/2012

November 11, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.