


CORNER RESTORATION

CORNER: S1/4 Cor. Sec. 31 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Bamford Robb

CONTRACT NUMBER: 366

CONTRACT DATE: August 18, 1880



Subsequent surveys:

- Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set basalt stone 16x12x10 in mound of stone for 1/4 sec. cor from which a juniper 24 in. dia. bears S5°W. 45 lks dist.

- 1975: Oviatt's and Rogers' field notes state: The 1/4 sec. cor. of secs. 6 and 31, monumented with the original basalt stone, 12x10x8 ins., firmly set 3 ins. in the ground, mkd. 1/4 on N. face from which the original bearing tree: A juniper, 36 ins. diam., bears S.8°W., 49 lks dist., with scribe marks 1/4 S BT visible on partially healed blaze. And a bearing tree of which I have no record: A juniper, 12 ins. in diam. bears N.69½°E., 36 lks. dist. with scribe marks 1/4 S BT visible on partially healed blaze. At the corner point Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd. From which a new bearing tree:

A juniper, 10 ins. diam. bears N.40½° W, 79 lks dist., mkd. 1/4 S31 BT deposit corner stone alongside iron post.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

NOV 3, 2010

BY:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2012

November 3, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.

RECORD MARKINGS ON BRASS CAP PER BLM FIELD NOTES

T16S R27E

1/4 $\frac{S31}{S6}$

T17S

1976