


CORNER RESTORATION

CORNER: SE Cor. Sec. 33 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Bamford Robb

CONTRACT NUMBER: 366

CONTRACT DATE: August 18, 1880



Subsequent surveys:
 ▶ Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set basalt stone 12x10x7 in mound of stone for cor to secs 33-34-3 & 4

- ▶ 1975: Oviatt’s and Rogers’ field notes state: *The cor. of sec. 3, 4, 33 and 34, monumented with the original basalt stone, 17x8x6 ins. (record 12x10x7 ins.) Loosely set in mound of stone, 1 ½ ft. base 6 ins. high mkd with 3 grooves on W. face, and 3 notches on E. edge. At the corner point: Set an iron post, 28 ins. long, 2½ ins. diam., 16 ins. in the ground to solid rock and in a mound of stone 3 ft. base, to top, with brass cap mkd. From Which:*
A juniper, 11 ins. diam., bears S.60°E., 40 lks. dist., mkd. T17S R27E S3 BT

A juniper, 14 ins. diam., bears S.44¾°W., 62½ lks. dist., mkd. T17S R27E S4 BT

A juniper, 8 ins. diam., bears N.10¾°W., 35 lks. dist., mkd. T16S R27E S33 BT

Deposit corner stone alongside iron post.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
 GRANT COUNTY SURVEYOR

OCT 28, 2010
 BY:

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

OREGON
 JULY 9, 2002
 MICHAEL C. SPRINGER
 #70918
 EXPIRES: 6/30/2012

October 28, 2010 Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.

RECORD MARKINGS ON BRASS CAP PER BLM FIELD NOTES

T16S R27E
 S33 | S34
 S4 | S3
 T17S
 1975