


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-7

History of original corner establishment:

Original Survey by Ramford Robb under GLO Contract No. 366, dated August 18, 1880.

Set stone 20x16x12 in mound of stone for 1/4 Sec. Cor.



Description of corner evidence found:

A diligent search was made and no evidence of the original corner could be found.

Description of monument and accessories I established to perpetuate the

original location of this corner: At surveyed point set 2½" x 30" galvanized pipe with brass cap stamped:
Set pipe 22" in ground with mound of stone to cap.


T16S R28E WM

1/4 S 20
 +
 S 29
 1979
OR PLS 1294

From which:

A P. Pine 5" in dia. bears N18°E, 15.1 ft., scribed 1/4 S20 BT.
A P. Pine 9" in dia. bears S7°E, 21.0 ft., scribed 1/4 S29 BT.

Attached 54-3 and 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's orange. Attached 54-4 sign to metal fence post 5 ft. west of corner.



I hereby certify the above corner monument was reestablished as herein described.

Witness: Rodger Orton
 Glen Wagoner
 Jeff Anderson

August 28, 1979

Office of.....County Surveyor..... County of... Grant
State of... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the... 4... day of... Oct... , 19..79
..... Robert D. Baggett by
(COUNTY OFFICIAL) (DEPUTY)