


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1880 by Bamford Robb, under General Land Office Joint Contract No. 366.

Surveyor General's records state:

Set post for $\frac{1}{4}$ sec. cor. from whcih a pine 6" dia. bears S12° E E 68 lks dist. Pine 30" dia. bears N84° W 28 lks dist.



Note: No restoration appears in County records.

Description of corner evidence found:

At assumed corner location, I found the remains of a charred stake 12" in the ground at record distance from a 34" (record 30") P. pine N 84° W 28 lks dist. and a dead and down 6" dia. P. p. S 12° E 68 lks dist. Scribing visible and readable on the bearing trees.

Description of monument and accessories I established to perpetuate the original location of this corner:

As evidence in vicinity of corner agrees with GLO original record, at the location of record call for bearing and distance from bearing trees and found portions of a charred post, I set a 30 inch long by 2 inch dia. galv. iron pipe in the ground, with 2 inch brass cap marked:

T16S R28E
1/4
S30 S29
1978
PLS 1067


New Witness Trees:

A Fir 10 inches dia. bears S 28° 30' E 14.2 feet dist. scribed $\frac{1}{4}$ S 29 BT

A Fir 5 inches dia. bears N 31° W 10.6 feet scribed $\frac{1}{4}$ S 30 BT

I placed a brass washer marked PLS 1067 and USFS signs on Bearing Trees. I hereby certify the above corner monument was re-established as herein described on June 1, 1978.

Witness: Johnny D. Smith



Office of *Surveyor* County of *Grant*
State of *Oregon*, I hereby certify that the within instrument was filed in this office
for record on the *21* day of *Sept*, 19*78*
Robert W. Bight by *Robert W. Bight*
(COUNTY OFFICIAL) (DEPUTY)