


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No original corner set.



Description of corner evidence found:

None originally set.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set by intersection, a 2 $\frac{1}{2}$ "x30" aluminum pipe with 3 $\frac{1}{4}$ " aluminum cap 24" in ground in mound of stone. Cap marked;

Bearing trees

a ponderosa pine 6" in diameter bears N 82°W 50.9 feet distance, scribed "C $\frac{1}{4}$ S17" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.

a ponderosa pine 6" in diameter bears S 03 $\frac{1}{2}$ °E 15.5 feet distance, scribed "C $\frac{1}{4}$ S17" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.

Compass declination 19° East

Note

I set a steel fence post at corner with USFS 154-9 sign, placed USFS bearing tree signs on all bearing trees, and painted red band on smooth bark at breast height on all bearing trees.

I hereby certify the above corner location was perpetuated as herein described on August 24, 1981.

Terry Butler Terry Butler, Witness

T16S R30E
C $\frac{1}{4}$ S17
1981
RLS 1664

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Carl E. Sundet
OREGON
JULY 14, 1978
CARL E. SUNDET
1664

Office of Sumner County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 23 day of Oct, 1981
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)