


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**History of original corner establishment:**

Corner originally established by S. W. Lackland, under joint contract #357, dated July 2, 1880.  
Surveyor General's records state: Set post with pits and mound .



**Description of corner evidence found:**

Found no evidence of original post, pits, or mound.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Set by single proportionate measurement a 2 1/2"x30" aluminum pipe with 3/4" aluminum cap, 26" in ground. Cap marked;

**Bearing trees**

a ponderosa pine 10" in diameter bears N 10° E 150.4 feet distance, scribed "1/4S16" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.

a ponderosa pine 16" in diameter bears S 19 1/2° W 139.6 feet distance, scribed "1/4S17" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.

Compass declination 18° East

**Note**

I set a steel fence post with USFS Attention sign at corner, placed USFS bearing tree signs on all bearing trees, and painted red band on smooth bark at breast height on all bearing trees.

I hereby certify the above corner location was perpetuated as herein described on July 16, 1981.

Terry Butler Terry Butler, Witness



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Carl E. Sundet

OREGON  
JULY 14, 1978  
CARL E. SUNDET  
1664

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 22 day of Oct, 1981.  
Robert D. Baggett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)