


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established under joint contract #357, dated July 2, 1880 by S. W. Lackland, interiors, and Bamford Robb, exteriors.

Surveyor General's records state: Set post in mound of stone. From which;  
a pine, 12" in diameter, bears N 30° E, 27<sup>5</sup> links



Description of corner evidence found:

No original evidence found.


Description of monument and accessories I established to perpetuate the original location of this corner: Set corner by single proportionate measurement. At corner location, I set a 2½" x 30" aluminum pipe with a ¾" aluminum cap 26" in ground. Marked;

Bearing trees

a ponderosa pine, 14" in diameter, bears S 50° W, 12.1 ft., scribed "¼ S24" in upper blaze and "BT" and brass washer stamped RLS 1664 in lower blaze.

a ponderosa pine, 14" in diameter, bears N 87° E, 27.8 ft., scribed "¼ S19" in upper blaze and "BT" and brass washer stamped RLS 1664 in lower blaze.

Compass declination 19° East



I certify the above corner location was perpetuated as herein described in January 1981.

Terry Butler Terry Butler, Witness

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Carl E. Sundet*

OREGON  
JULY 14, 1978  
CARL E. SUNDET  
1664

Office of..... Surveyor ..... County of..... Grant .....  
State of..... Oregon ..... I hereby certify that the within instrument was filed in this office  
for record on the..... 13 day of..... Feb ..... , 19..... 81  
..... Robert A. Bayliff ..... by .....  
(COUNTY OFFICIAL) (DEPUTY)