


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established under joint contract #357, dated July 2, 1880, by S. W. Lackland, interiors, and Bamford Robb, exteriors.

Surveyor General's records state: Set post with pits and mound.



Description of corner evidence found:


None found.

Description of monument and accessories I established to perpetuate the original location of this corner: Set corner by single proportionate measurement. At corner location, I set a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap 26" in ground, marked;

Bearing trees

a ponderosa pine, 13" in diameter, bears N 30° W, ft., scribed "1/4 S20" in upper blaze and "BT" and brass washer stamped RLS 1664 in lower blaze.

a ponderosa pine, 18" in diameter, bears S 29° W, 170.6 ft., scribed "1/4 S29" in upper blaze and "BT" and brass washer stamped RLS 1664 in lower blaze. Compass declination 19° East



I certify the above corner location was perpetuated as herein described in January 1981.

Terry Butler Terry Butler, Witness

REGISTERED PROFESSIONAL LAND SURVEYOR

Carl E. Sundet

OREGON JULY 14, 1978 CARL E. SUNDET 1664

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 13 day of Feb, 1981
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)