

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by S. W. Lackland, US Deputy Surveyor, during the original survey Joint Contract No. 357 dated July, 1880.

Set post for 1/4 sec cor with pits and mound as per instruction.

DIAGRAM

T16S R30E

S21
1/4 ---
S28

1986
FLS 699

Description of corner evidence found:

Corner location falls in meadow hay field with a ditch nearby. No evidence of the original corner was found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3/4" aluminum cap, marked as shown in the diagram, 30" in the ground to be flush so as to not interfere with haying operations, at single proportionate measurements from adjacent found corners. No mound necessary.

No new bearing trees set because no trees are available.

Deposited two color-coded magnetic memorials 3' from the monument with silver to the ENE and blue to the WSW 18° in the ground to be below any agricultural activity. Reference Monuments are impractical at this corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on June 20, 1986, I re-established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 30 DAY OF Sept, 1986

Grant County Surveyor