

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**History of original corner establishment:**

Corner was established by S. W. Lackland, US Deputy Surveyor, during the original survey Joint Contract No. 357 dated July, 1880.

Set post for 1/4 sec cor with pits and mound as per instruction.

**DIAGRAM**

T16S R30E

526  
1/4 ---  
535

1986  
PLS 699

**Description of corner evidence found:**

The corner location falls at the edge of a field about 10' from Damon Creek. No evidence of the original corner was found.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at single proportionate measurements from adjacent found corners. No mound because no rocks were available..

No new bearing trees set because no trees are available.

1"x30" galv. pipe with 2 1/2" alum. cap Reference Monument bears N42° 30'W, 8.3 feet marked RM 8.3' ↘ 1986 PLS 699.

1"x30" galv. pipe with 2 1/2" alum. cap Reference Monument bears S47° 15'W, 8.7 feet marked RM 8.7' ↗ 1986 PLS 699.

Set a steel fence post 3 feet W of the corner with a Land Survey Monument sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on May 30, 1986, I re-established the corner as herein described.

**FILED**

IN THE OFFICE OF THE Grant COUNTY SURVEYOR  
THIS 30 DAY OF Sept, 1986

Robert D. Dwyer  
Grant County Surveyor

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Leland L. Myers*

OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699