


CERTIFIED RECORD OF LAND CORNER MONUMENTATION.

History of original corner establishment:

Corner established in 1880 by S. W. Lackland under General Land Office Contract No. 357
Surveyor General Record states:
Set post for 1/4 section corner from which:
A pine 24 ins. diam. bears N. 5° E., 22 lks.
A pine 20 ins. diam. bears N. 40° W., 16 lks.



Description of corner evidence found:


Found Original BT's:
from corner position:
A pine 34" diam. bears N. 20° E., 14.5 feet no scribing visible in closed blaze. I did not open.
A pine 33" diam. bears N. 34° W. 10.6 feet marked 4SBT in partially closed blaze.
Measured to face of original BT's. No evidence of original post was found.

See record Map of Survey No. 881

Description of monument and accessories I established to perpetuate the original location of this corner:

At record distance from original BT's I set a 2 1/2"x30" aluminum pipe with aluminum cap buried 24" in ground marked as shown.

MONUMENT MARKED



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

Corner set by: R.D. Bagett
Witnesses : J.L. Watson
T.R. Steele

July 2, 1985

Painted 6" red band around BT's above blaze and attached BT sign and attention sign to BT's. Set steel fence posts approx. 5 feet North from Monument and attached appropriate signs as called for in my contract. Used magnetic compass with 20° E. var. and steel tape measuring to face of blaze of original BT's.

Office of..... Surveyor..... County of..... Grant
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 14 day of Sept, 1985
Robert D. Bagett by
(COUNTY OFFICIAL) (DEPUTY)