


CERTIFIED RECORD OF LAND CORNER MONUMENTATION.

History of original corner establishment:

Corner not established previously



Description of corner evidence found:

NONE

See Record Map of Survey No. 881


Description of monument and accessories established to perpetuate the original location of this corner:

At corner point I set a 2¹/₂x30 inch aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, From which:

A pine 10 ins. diam. bears S. 12° W., 40.6 feet, marked C¹/₄S32BT.

A pine 13 ins. diam. bears N. 82° W., 11.1 feet, marked C¹/₄S32BT.

MONUMENT MARKED



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

Corner set by: R. D. Bagett
Witnesses : J. L. Watson
T. R. Steele

July 18, 1985

Nailed brass washer marked OPLS 598 to lower blaze of new BT's. Painted 6" red band around new BT's above blaze and attached BT sign and attention sign to BT's. Set steel fence posts approx. 5 feet North & South from monument, and attached appropriate signs as called for in my contract. Used magnetic compass with 20° E. var. and steel tape measuring to a 40d nail driven in side center at root crown of BT's.

Office of.....Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 14 day of Sept, 1985
Robert D. Bagett by
(COUNTY OFFICIAL) (DEPUTY)