

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

Corner was established by S. W. Lackland, US Deputy Surveyor, during the original survey Joint Contract No. 357 dated July, 1880.

Set post for 1/4 sec cor with pits and mound as per instruction.

**DIAGRAM**

T16S R30E

1/4  
S35 | S36

1986  
FLS 699

**Description of corner evidence found:**

Corner location falls in primitive access road near a three-way fence corner. No evidence of the original corner was found.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Set a 2"x30" aluminum pipe with a 3/4" aluminum cap, marked as shown in the diagram, 30" in the ground to be flush with the primitive road surface, at single proportionate measurements from adjacent found corners. No mound necessary, from which new BTs are:

42" Ponderosa pine bears S19° 30'W, 200.8 feet scribed 1/4 S35 BT

35" Ponderosa pine bears S4° 15'E, 229.6 feet scribed 1/4 S36 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped FLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set steel fence posts 22 feet S and 23 feet W of the corner on the National Forest property lines. Attached Forest Boundary signs to each post and an Attention sign to the S post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on June 27, 1986, I re-established the corner as herein described.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699

**FILED**

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 30 DAY OF Sept, 1986

Leland L. Myers  
Grant County Surveyor