


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



A-3

F.B. 6 P. 27-28

Description of corner evidence found:

None. Corner not previously established.

Description of monument and accessories | established to perpetuate the original location of this corner:

At position as determined by survey set a 2-1/2" O.D.x30" long aluminum pipe 24" in ground with a 2-1/2" diameter aluminum cap marked as shown: Raised a 2-1/2 ft. diameter stone mound to cap.


Marked bearing trees:

A 13" Ponderosa Pine bears South 25-1/2° East, 11.2 ft., scribed "1/4S6BT"; a 9" Ponderosa Pine bears South 46-1/2° West, 16.0 ft., scribed "1/4S6BT". Painted a 6" red band and face blazes red. Nailed signs 54-9 and 54-3 to BT'S. Nailed a brass washer stamped "LS 1026" to face blazes of BT'S. Set a steel fence post 5 ft. South of cap with sign 54-9. Bearings are by staff compass and declination is 19-1/2° East.


I hereby certify that the above corner monument was re-established as herein described on October 13, 1989.

Witnesses: David B. Armstrong

See C.S. #1122



David B. Armstrong



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 13 day of Feb, 1990
Donald Leggett by _____
(COUNTY OFFICIAL) (DEPUTY)