

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. E-7

History of original corner establishment:

Corner was originally established by Samuel W. Lackland, in 1881, under General Land Office Contract No. 384.

The U.S. Surveyor Generals Notes State: Set stone 16x8x5 in mound of stone for 1/4 sec. cor.

DIAGRAM

T16S R32E
S5
1/4-.-
S8
1987
RLS 848

Description of corner evidence found:

Examined all the stones in the area, no evidence is found.

No accessories are originally established. Corner is lost to fencing activity over the years. Established 1/4 corner position at proportionate measure between the section corner as previously established at proportionate measure, 1/2 mi. East and the corner as found 1/2 mi. West.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 28" in the ground.

From Which:

A Pine 14" dia., Bears N41°W., 58.4 ft., scribed: 1/4 S5 BT

A Juniper 12" dia., Bears S 6°E., 39.1 ft., scribed: 1/4 S8 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, East & West 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1988
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: May 2, 1987
Refer to Map of Survey No. 997

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 24 day of July, 1987
Robert M. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)