

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. E-11

History of original corner establishment:

Corner was originally established by Samuel W. Lackland, in 1881, under General Land Office Contract No. 384. The U.S. Surveyor Generals Notes State: Set stone 15x12x5 in mound of stone for 1/4 sec. cor.

DIAGRAM

T16S R32E
S4
1/4--
S9
1987
RLS 848



Description of corner evidence found:

Found 12"x10"x7" stone, with "1/4" marked on the face, set in an old mound of stone.

There are no accessories originally established. Accepted the above described stone as the 1/4 Sec. Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 28" in the ground.
From Which:
A Pine 16" dia., Bears S89°W., 37.1 ft., scribed: 1/4 S9 BT
A Pine 13" dia., Bears N68 1/2°W., 76.3 ft., scribed: 1/4 S4 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, East and West 4 ft. from the corner.



This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: May 2, 1987
Refer to Map of Survey No. 997

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 24 day of July, 1987
Douglas M. Ferguson by _____
(COUNTY OFFICIAL) (DEPUTY)