

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was established in 1980 by Tyler B. Parsons for the U.S. Forest Service as recorded in County Survey 638.

DIAGRAM

T16S R32E
NN 1/64
S26 | S25

Description of corner evidence found:

Monument was found disturbed by agricultural activity and was lying on the ground in the vicinity of the original position.

Description of monument and accessories established to perpetuate the original location of this corner:

I reset the monument by survey between the section and quarter corners between Sections 25 and 26. The monument falls in approximately the same hole as originally set.

Reset 2-1/2" brass cap on iron pipe 30" long, 30" in the ground (flush). I defaced the original date and added township, range and date.

N-N
1/64
T16S R32E
S26 | S25
PLS 1918
XXXX
1984

Bearing Trees:

Set 9" Ponderosa Pine bears N60-1/40E, 71.5 ft., scribed NN1/64S25BT, with 3/4" brass washer "LS 1918".

Set 10" Ponderosa Pine bears S130W, 128.4 ft., scribed NN1/64S26BT, with 3/4" brass washer "LS 1918".


Painted faces and bands on bearing trees and attached Attention and bearing tree tags. Steel fence post with Attention and Boundary signs set North 6 ft.

This corner was reset 10 October 1984

Witnessed by: Louise Parsons

Road Cadastral Survey, Cont. No. 53-04H1-4-9665N.

Tyler B. Parsons
Professional Land Surveyor
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515



Office of Surveyor County of Grant
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 29 day of Nov, 1984
Robert D. Bayne by _____
(COUNTY OFFICIAL) (DEPUTY)