

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1880 by Bamford Robb
under General Land Office contract #357
Surveyor General record states;

Set post for Sec. cor. with pits and mound

DIAGRAM

T16S

R31E

R32E

S 25

S 30

S 36

S 31

No record of subsequent remonumentation found in County records
Description of corner evidence found:

NONE--- area is in hay field


See map of survey dated October, 1981

Description of monument and accessories I established to perpetuate the
original location of this corner:

At proportionate distance I set a 2½ x 30 inch aluminum pipe with aluminum cap
marked as shown 30 inches in the ground, from which;

A 1"x72" steel fence post bears East, 4.2 feet,

A 1"x72" steel fence post bears South 5.9 feet



Date, October 7, 1981.

Brass washer nailed to BT blaze. Used
steel tape and magnetic compass with 20°
East declination in the establishment of
accessories. Original BTs measured to
face of blaze. New BTs measured to center
of tree.

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 23 day of Dec, 1981
Robert D. Dugan by _____
(COUNTY OFFICIAL) (DEPUTY)