


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(16)
2

History of original corner establishment:

Corner established in 1881 by Samuel W. Lackland
under General Land Office contract # 384
Surveyor General record states;
Set stone 14x6x4 in mound of stone for
1/4 Section corner



No record of subsequent remonumentation found in County records
Description of corner evidence found:

NONE-- area is now a hay field

See map of survey dated October, 1981
**Description of monument and accessories I established to perpetuate the
original location of this corner:**

At proportionate distance I set a 2 1/2 x 30 inch aluminum pipe with
aluminum cap marked as shown 30 inches in the ground from which;


A 1" x 72" steel fence post bears East, 6.6 feet,

A 1" x 72 " steel fence post bears South 6.1 feet

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Duane I. Griffith

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644



Date. October. 7, 1981.

Brass washer nailed to BT blaze. Used
steel tape and magnetic compass with 20°
East declination in the establishment of
accessories. Original BTs measured to
face of blaze. New BTs measured to center
of tree.

Office of... *Surveyor* ... County of... *Grant* ...
State of... *Oregon* ... I hereby certify that the within instrument was filed in this office
for record on the... *23* day of... *Dec* ... , 19... *81* ...
Robert D. Baggett by ...
(COUNTY OFFICIAL) (DEPUTY)