


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Samuel W. Lackland
under General Land Office contract # 384
Surveyor General record states;

Set stone 18x12x10 ins. in mound of stone for Sec. Cor.



No record of subsequent remonumentation found in County records
Description of corner evidence found:

Found marked stone, call size, in mound of stone.




See map of survey dated October, 1981
Description of monument and accessories I established to perpetuate the original location of this corner:

In place of stone, I set a 2½ x 30 inch aluminum pipe with aluminum cap marked as shown 20 inches in the ground from which;

A 1" x 72" steel fence post bears East, 5.0 feet
A 1" x 72" steel fence post bears South 5.6 feet

Buried stone West and along side pipe

Raised mound of stone



Date, October 7, 1981.

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. Original BTs measured to face of blaze. New BTs measured to center of tree.

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 23 day of Dec, 1981
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)