

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey

DIAGRAM

T16S	
R31E	R32E
N 1/16	
S 36	S 31

No record of subsequent monumentation found in County records

Description of corner evidence found:

NONE

See survey dated October, 1981

Description of monument and accessories established to perpetuate the original location of this corner:


At corner point I set a 2½ x 30 inch aluminum pipe with aluminum cap marked as shown 30 inches in the ground from which;

A 1" x 72" steel fence post bears East, 5.5 feet

A 1" x 72" steel fence post bears South, 5.0 feet

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Robert D. Baggett
OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644



Date. .October.7, 1981.

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. New BTs measured to center of tree.

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*23* day of.....*Dec*....., 1981.
Robert D. Baggett by.....
(COUNTY OFFICIAL) (DEPUTY)