

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. A-11

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T15S R34E
1/4 S4
T16S R33½E
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

Ponderosa Pine, 16" dia., bears S40°15'E, 70.4 ft., scribed: 1/4 S4 BT
Ponderosa Pine, 14" dia., bears S17°22'E, 81.8 ft., scribed: 1/4 S4 BT
Ponderosa Pine, 10" dia., bears S21°32'W, 25.9 ft., scribed: 1/4 S4 BT
Ponderosa Pine, 12" dia., bears S49°10'W, 40.4 ft., scribed: 1/4 S4 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) sign 5' north of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Susan E. Newstetter

OREGON
JULY 25, 1989
SUSAN E. NEWSTETTER
2405

Renewal Date: 12/31/94

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul and
Rick Pewonka
September 27, 1993
Refer to Grant Co. Survey No.: 1283

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 21 day of Jan, 1994
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)