

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-12

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T16S R33½E
E 1/16
C—C
S4
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

Ponderosa Pine, 18" dia., bears N29°41'W, 21.8 ft., scribed: C-E 1/16 S4 BT
Ponderosa Pine, 12" dia., bears S61°26'E, 54.3 ft., scribed: C-E 1/16 S4 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north and south of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1980
SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul and
Rick Pewonka
September 23, 1993
Refer to Grant Co. Survey No.: 1283

Renewal Date: 12/31/94

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 21 day of Jan, 1994
Robert D. Bayliff by _____
(COUNTY OFFICIAL) (DEPUTY)

C-12