

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original corner was established in 1884 by Henry W. Cooke under Contract No. 494. The original notes state:

"Set a basalt stone 16x14x8 ins 11 ins in ground for 1/4 sec cor marked 1/4 on W. face. dug pits 18x18x12 ins N & S of cor 5½ ft dist and raised a mound of earth 1½ ft high 3½ ft base alongside."

DIAGRAM

T16S R33½E
1/4
S26 | S25

Description of corner evidence found:

Found no evidence of the original corner monument or accessories.

Description of monument and accessories I established to perpetuate the original location of this corner:

Re-established this corner by single proportion, there being no evidence of the original monument or accessories. Set a 3¼" x 30" aluminum monument 20" in the ground in a mound of stone.

T16S R33½E
1/4
S26 | S25
PLS 1918
1985


Set a 2" aluminum cap on 3/4"x30" rebar West 10.0 ft, stamped
RM 1/4 S26 EAST 10.0 PLS1918 1985.

Set a 2" aluminum cap on 3/4"x30" rebar S30°E, 10.0 ft, stamped
RM 1/4 S25 N30W 10.0 PLS1918 1985.

Basis of Bearings - solar observation.
Work performed 6/15/85.

Witnesses: Louise H. Parsons, Douglas T. Parsons.
Road Cadastral Survey for the USDA, Forest Service.

Tyler B. Parsons
Professional Land Surveyor
1915 S.E. Stone St.
Corvallis, OR 97333
(503) 752-7515



Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the *22* day of *Aug*, 19*85*.
Robert D. Skyles
(COUNTY OFFICIAL) (DEPUTY)