

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. V-19

History of original corner establishment:

This corner was originally established by Henry W. Cooke, in 1884, under GLO Contract No. 494. Surveyor General Field Notes state:

Set a post 3½ ft. long 3 ins. square with marked stone 12 ins. in ground for 1/4 sec. cor marked 1/4 S on N face dug pits 18x18x12 ins. E & W of cor. 5½ ft. dist. and raised a mound of earth 1½ ft. high, 3½ ft. base around post.

DIAGRAM
T16S R33½E
S26
1/4 —
S35
1993
PLS 2405

Description of Corner Evidence Found:

Searched for not found. Area appears to have been farmed in the past and I believe the post and pits were lost to this farming.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

As references set 5/8"x30" rebars, with yellow plastic caps marked PLS 2405, 28 inches in the ground, at the following bearing and distance:

N44°26'W, 10.5 ft., no grooves on rebar
N51°23'E, 10.6 ft., 1 groove on rebar
S47°33'E, 9.7 ft., 2 grooves on rebar
S46°59'W, 8.8 ft., 3 grooves on rebar

Measurements to rebars taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south of the monument.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul and
Rick Pewonka
October 6, 1993
Refer to Grant Co. Survey No.: 1311

Renewal Date: 12/31/94

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 28 day of Mar, 19 94
Robert D. Boyer by _____
(COUNTY OFFICIAL) (DEPUTY)