


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by Henry W. Cooke in 1884.
Set: wooden post 3½' long X 3" square with marked stone 24"
in ground for ¼ sec. cor. marked ¼ on W face dug pit 18X18X12
N & S of corner 5½' away, and raised a mound of earth 1½'
high X 3½' around post.
No bearing trees marked.




Description of corner evidence found:

No trace of original monumentation found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2½"X30" alum. pipe with alum. cap set 24" in ground.
Marshy area with no rocks or trees.
Variation 17° E with staff compass.
Witnessed by Randall Schulson Aug. 1983.
SET STEEL FENCE POSTS 5' NORTH & 5' WEST.

Alum. cap stamped as shown:



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald H. Schulson

OREGON
JULY 14, 1978
RONALD H. SCHULSON
1658

Office of..... Surveyor County of..... Grant
State of..... Oregon I hereby certify that the within instrument was filed in this office
for record on the... 30 day of... Nov 19... 83
Ronald H. Schulson by
(COUNTY OFFICIAL) (DEPUTY)