CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by S. W. Lackland, US Deputy Surveyor, during the original survey Joint Contract No. 357 dated July, 1880.

Set post for cor Secs 21, 22, 27 & 28 with pits and mound as per instruction.

DIAGRAM

T16S R30E

S21	S22
S28	S27

1986
PLS 699

Description of corner evidence found:

The corner location falls in a meadow hay field. No evidence of the original corner was found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3¼" aluminum cap, marked as shown in the diagram, 30" in the ground to not interfere with haying operations, at double proportionate measurements from adjacent found corners..

No new bearing trees set because no trees are available.

Set 4 color coded DEEP magnetic memorials 3' from the monument with orange in the NW, silver in the NE, purple in the SE, and blue in the SW quadrants 18" in the ground to be below any agricultural activity.

A 45° angle in an irrigation ditch bears S40°W, 27.5 feet from the monument and the monument is 4 feet NW of same ditch.

Reference Monuments are impractical at this corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on June 10, 1986, I re-established the corner as herein described.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 20 DAY OF June, 19 86

Robert D Bagett

Grant County Surveyor

USDA-FS Contract No. 53-04H1-5-0125N

T16S R30E R-13