# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**History of original corner establishment:**

Original survey by George R. Campbell in 1900-1902.
Set: pine post marked "¼ S3."
20" black pine, S67°E, 19 links= 12.54'

**DIAGRAM**

T15S R35E
N 1/4 SEC. 3
T16S R34E
N

Henry W. Cooke surveyed Section 3 in 1884, but did not set the North ¼ corner.

**Description of corner evidence found:**

No evidence of original post found.
Roots of original 20" pine S67°E, 12.5' to face, no scribing visible.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Set a 2½"X30" alum. pipe with alum. cap 28" in ground in stone mound at the position determined from roots of BT which agrees with the orig. creek calls to the West. From which point bear the following bearing trees which I marked:

10" Lodgepole pine, S83 3/4°W, 93.1' to face, 93.6' to CL, marked:"¼ S3 BT".
8" Lodgepole pine, S51°E, 10.9' to face, 11.3' to CL, marked:"T16S R34E ¼ S3 BT"

Above BT's have painted red faces and bands, USFS signs and brass washers marked LS 1658 attached to lower portion of face.
Variation 17°E using staff compass.
Witnessed by Randall Schulson Aug. 1983.

Alum. cap stamped as shown:

LS1658
T15S R35E
1/4 S3
T16S R34E
1983

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald H. Schulson
OREGON
JULY 14, 1978
RONALD H. SCHULSON
1658

Office of.....Surveyor..... County of....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the....30.... day of.....Nov....., 19...83
.....Robert D. Lazzarini..... by .....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

A-15