CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by George R. Campbell in 1900-1902.
Set: basalt stone 12X10X6, marked ¼ on South face.
9" white fir S67°W, 0.10 ch. = 6.6'

DIAGRAM

N

T15S R35E
1/4 SEC. 2
T16S R34E

Henry W. Cooke surveyed Section 3 in 1884, but did not set the North ¼ corner.

Description of corner evidence found:

Found original stone 12X10X4 with no marks visible, North face appears to have been chipped off. 13" W. fir, S67°W, 6.6'.

Description of monument and accessories I established to perpetuate the original location of this corner:

2½" X 30" alum. pipe with alum. cap set 22" in ground in a stone mound. Original stone buried flush with ground North of pipe.

8" W. fir S46¼°E, 26.2' to face, 26.5' to CL, mkd:"¼ S2 BT"
Above trees has painted red face and band, USFS signs and brass washer stamped LS 1658 attached to lower portion of face. TAG ON NEW BT ONLY
Variation 17°E using staff compass.
Witnessed by Randall Schulson AUG. '83.

Alum. cap stamped as shown:

LS 1658
T15S R35E
1/4 S2
T16S R34E
1983

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald H. Schulson

OREGON
JULY 14, 1978
RONALD H. SCHULSON
1658

Office of County Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 30 day of NOV. 1983

Robert D. Bryant by .....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

A-19